

BERGER PRODUCT SPECIFICATIONS

LUXATHANE 5060

Polyurethane Durable Finish

PRODUCT DESCRIPTION

A two-component, aliphatic isocyanate cured polyurethane coating with exterior durable finish.

DESIGN FEATURES

A high performance finishing coat for structural steel in aggressive and corrosive environments.

As a finishing or maintenance coat for the exterior of chemical storage tanks, pipes, etc.

Also suitable as a finishing coat for concrete & plastered surfaces in areas where high durability is required

Excellent colour and gloss retention and overall durability properties.

Long term re-coatability properties.

Resistant to spillage or splashes of mild chemicals.

Suitable for use over a wide range of substrates e.g. steel, concrete, wood, gypsum etc.

PHYSICAL CHARACTERISTICS

	Recommended Application Data	Wet [µm]		Dry [μm]	m²/l		
	Theoretical Coverage	96		50	10.40		
Volume solids		48% (based on ASTM D2697)					
Dry Film Thickness Range		40 μm					
Flash Point		29 °C					
Finish		Gloss, Semi-gloss, Low Sheen & Matt					
Colour Range		Please refer to our Standard Colour Card					
Packing		5 litres set (4.5 litres Base: 0.5 litres Hardener)					
Mix R	9 Base : 1 Hardener						

APPLICATION METHOD

AIRLESS SPRAY Recommended method of	Tip Size	:	0.43– 0.53 mm	(17 -21 thou)			
application	Pressure	:	110 –160 kg/cm ²	(1600 – 2300 psi)			
CONVENTIONAL AIR SPRAY	May be used.						
BRUSH OR ROLLER	May be used. However, additional coats may be required to achieve the recommended film thickness. Suitable for stripe coating, weld-seams, edges, corners, rivets, etc.						

DRYING & CURING TIME

Ambient	Touch Dry	Hard Dry	Overcoating Interval		Pot Life
Temperature			Minimum	Maximum	
15 °C	3 hours	10 hours	10 hours	Indefinite	4 hours
25 °C	2 hours	6 hours	6 hours	Indefinite	2 hours
35 °C	1 hour	3 hours	3 hours	Indefinite	1 hour

USEFUL INFORMATION

THINNER : SOLVALUX 7-73 (Maximum 10% addition)

CLEANER : SOLVALUX 7-77

STORAGE : Store in a cool dry shaded area.

SHELF LIFE AT 25 °C 12 months minimum when stored as prescribed in the MSDS.



BERGER PRODUCT SPECIFICATIONS

SURFACE PREPARATION

The service life span and the service performance of LUXATHANE 5060 is directly related to the degree of surface preparation.

STEEL

- For optimum performance, this product should be applied to a surface that has been blast cleaned and suitably primed and built
- This coating is usually applied over a suitable primer and undercoat or build-coat. This
 underlying system should be sound and undamaged.
- Ensure that the surface to be over-coated is clean, dry, and free from dust, grease and oil, or any other surface contaminants.
- Always ensure the maximum over-coating time for the primer or build-coat has not been exceeded prior to application.

ALUMINIUM, GALVANISED STEEL

 Degrease with SOLVALUX 7-45 and where practical abrade lightly to increase anchoring sites and improve adhesion. Pre-treat with one coat of LUXAPRIME 1500 followed by one coat of a suitable build coat, e.g.EPILUX 218.

To avoid condensation of moisture onto substrate prior to coating application, relative humidity should not exceed 85% and substrate temperature should be more than 3 °C above Dew Point.

SUITABLE UNDERCOATS

Epilux 610, Epilux 78, Epilux 171, Epilux 800, Luxaprime 1501, Luxaprime 1801, Epilux 218, Epilux 58, Epilux 58HS, Epilux 82, Epimastic 3000HS, Epimastic 3100, Epimastic 5100, Epimastic 7100

NOTES

- The coating specifications given above are typical. For specific recommendations to suit individual applications, please refer to your Berger Paints representative.
- Condensation occurring during or immediately after application may result in a drop in gloss and inferior film properties.
- This product is not suitable in use in immersed conditions.
- Do not apply this product when the pot-life is exceeded, even if the paint still appears liquid.
- Premature exposure to ponding-water will cause colour change, especially with dark colours and at low temperatures.

SAFETY PRECAUTION

Avoid contact with eyes and skin. Wear suitable protective clothing such as overalls, goggles, dust mask and gloves. Use barrier cream.

Ensure that there is adequate ventilation in the area where the product is being applied. Do not breathe in vapour or spray mist.

This product is flammable. Keep away from sources of ignition. Do not smoke.

Take precautionary measures against static discharge.

In case of fire, blanket flames with foam, carbon dioxide or dry chemicals.

FIRST AID

Eyes : In the event of accidental splashes, flush eyes with warm water immediately

and seek medical advice.

Skin: Wash skin thoroughly with soap and water or approved industrial cleaner.

Do Not Use solvents or thinners.

Inhalation: Remove to fresh air, loosen collar and keep patient rested.

Ingestion: In case of accidental ingestion, DO NOT INDUCE VOMITING. Obtain

immediate medical attention.

For further safety information, please refer to our Material Safety Data Sheet (MSDS)

DISCLAIMER

The information provided on this data sheet is not intended to be complete and is provided as general advice only. It is the responsibility of the user to ensure that the product is suitable for the purpose for which he wishes to use it. As we have no control over the treatment of the product, the standard of surface preparation of the substrate, or other factors affecting the use of this product, we are not responsible for its performance nor would we accept any liability whatsoever or howsoever arising from the use of this product unless specifically agreed to in writing by us. The information contained in this data sheet may be modified by us from time to time, and without notice, in the light of our experience and continuous product development.

LUXATHANE 5060 REVISION 03-2012 G1